ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar

Street ID	Street Name	Significant Landmark
W0401, W0404, W0623, W0421, W0302, W0409, W0405, W	NA, Vidya Nursary School & Raj Colony Rd, 8th A Crs, 3rd Crs Lakshmi Sagar Lyt	Singapura layout Cross road

Segment No.	Total Length (m)
11/C-W0401/S030458	591.28

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	27.13	77.540016	13.076767	77.539993	13.076523	W0404	W0263
2	285.60	77.539894	13.076919	77.542433	13.076382	W0292	DEAD END
3	278.55	77.539939	13.077120	77.542470	13.076692	W0404	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Road Development and asphalting work at Singapura layout Cross road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1999000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Road Development and asphalting work at Singapura layout Cross road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000034

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-PMT/61/2015-16	29/04/2015	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/07/2015	29/07/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N KEERTHI		0.00

Phone No.	E-Mail ID
9731567144	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH
Date of Inspection	**Remarks**	
18/03/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	11	Ward Name:	Kuvempu Nagar	Street ID:	W0401, W0404, W0623, W0421,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	VASU K M	18/03/2017	17/04/2017	COMPLETED
AEE	MAHADEV	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0401, W0404, W0623, W0421,